



- 1. ASSEMBLY MUST BE PERFORMED BY A COMPETENT GUNSMITH. 2. DRILL BLIND HOLES 180° FROM GAS PORT.
- 3. LOCATE 1 ST HOLE .300" FROM BARREL SHOULDER. 4. DRILL TO APPROPRIATE DEPTH AS INDICATED BELOW.
- 5. INSTALL GAS TUBE INTO MANIFOLD.
- 6. INSTALL MANIFOLD ONTO RIFLE, USE OF LOCTITE IN NOT REQUIRED **BUT IS RECOMMENDED**





RECOMENDED: Apply a small amount of #262 (red) Loctite to the set screws and around the gas port.

	Unless otherwise specified Diminsions are in Inches TOLERANCES: ANGLES ± 30° FRACTIONS ±.015 .0001 .000005 .00000005	BADGER ORDNANCE							
		1209 Swift St 816 421-4956			Ŀĸ	N. Kansas City, MO. 64116 FAX 816 421-4958			
		TDX Manifold assy							
			Dwg No. 249	-69-1	Part No.	249-6 249-7	-	Date 2 Jan 2016	
	ENGINEER: M. BORDSON	Scale NTS		Matl: S	tainless	steel	Pa	ge 1 of 1	